Home Inspection REPORT SUMMARY

51 Alvin Avenue, Toronto

Prepared by: Gordon Mathieu B.Sc Elec Eng, MBA Date: October 17, 2020



Setting the Standard since 1978

416-964-9415 inspection@carsondunlop.com carsondunlop.com

A digital version is available at: www.prelistingreport.com/2020/51-Alvin-Ave.pdf



Home Inspection REPORT SUMMARY

This Report Summary reflects the key findings of our inspection at 51 Alvin Avenue, Toronto.

ABOUT THE HOME

This well-built approximately 90-year-old detached home (a triplex) is in good condition overall and has been maintained.

- Roofing The 4-year-old asphalt shingles can typically last 20 to 25 years. These are better than average quality.
- Exterior Several components have been updated. The masonry is in good condition overall.
- Structure The masonry exterior walls are supported by a concrete block foundation. No structural issues were found.
- Electrical The 2x100-amp electrical service is suitable for a home of this size: there are 2 meters & 2 breaker panels. Ground fault interrupters were noted in many outlets.
- Heating The system includes a 27-year-old gas-fired mid-efficiency boiler with a typical life expectancy of 20 to 35 yrs.
- Cooling Several window units were noted.
- Insulation The attic insulation has been upgraded. This should help control energy consumption & costs.
- Plumbing The visible supply plumbing in the home is copper, including the upgraded main water service line. Copper is the preferred supply piping material.
- Interior Good quality interior finishes were noted throughout the home. The kitchens & bathrooms have been updated at some point. The basement has been partially finished and there is an apartment with a kitchen & bathroom. There are 2 sets of stairs in the home: front & right side/middle.

ITEMS THAT MAY REQUIRE ATTENTION

- **Electrical** Eventual updating of the knob & tube wiring, particularly when renovating, should be anticipated. The cost will depend on approach & extent of work: \$1,000 \$2,000 per room is common.
- Heating Although the boiler is close to the end of its life, continue to use and maintain the unit until it fails: cost of new \$6,000 to \$12,000.
- Interior Most windows are original: upgrading will be a major cost.
- Interior Evidence of dampness/leakage was noted in the basement which is a common issue. It can be minimized with downspouts & lot grading that direct water away from the building. Further evaluation.

FOR THE BUYER

The first step is to review this Report Summary, which provides an unbiased overview of the home, based on our inspection. This Summary is very helpful, but not enough to make a home buying decision. The second step is to review the complete inspection report and attend an On-site Review with the inspector – contact us at 416-964-9415. The fee is roughly half the cost of a standard inspection. Without the second step, our liability is limited to the party for whom we performed the inspection.

What is a Home Inspection?

A home inspection and report is an in-field performance evaluation conducted to provide information about the present functional condition of the home, based on a visual inspection of the readily accessible features.

About the Report Summary

This Summary reflects the key findings from our inspection, but it is not a home inspection report, and it does not contain all the information provided in the full report.

The Carson Dunlop Difference

We are a consulting engineering company that has been a leader in home inspection since 1978. As Canada's oldest and largest home inspection company, we have performed tens of thousands of inspections. We have been involved in shaping the profession, and we provide education and report writing systems to inspectors across North America. We are passionate about homes and are committed to delivering outstanding value and exceptional customer service.

Setting the Standard since 1978

416-964-9415

inspection@carsondunlop.com carsondunlop.com

